


1



2



3



Do not apply soldering iron to terminals for longer than 5 seconds

Ne pas appliquer fer à souder aux terminaux pour plus de 5 secondes

Nicht anwendbar lötkolben zu Terminals für länger als 5 Sekunden


No se aplicará hierro de soldar a las terminales durante más de 5 segundos



4



?





Caframo Limited
501273 Grey Road 1
Georgian Bluffs, ON
N0H 2T0
Canada












Toll Free / Sans Frais : 1-800-567-3556
Tel / Tél : 1-519-534-1080
www.caframo.com

Caframo
 Motor Replacement Instructions
 for Ecofan and Alcona

Instructions pour kit de rechange
 de moteur pour Ecofan et Alcona

Model 800CA Model 802CA
 Model T805

Model / Modèle
 800CA 802CA T805



Do not apply soldering iron to terminals for longer than 5 seconds

Ne pas appliquer fer à souder aux terminaux pour plus de 5 secondes

Nicht anwendbar lötkolben zu Terminals für länger als 5 Sekunden

No se aplicará hierro de soldar a las terminales durante más de 5 segundos